

Complaint Verification Report

Details of Complaint:- Sh. Kishanlal Gurjar through telephone on dated 09.04.2026, has informed that water was seeping out from the boundary of the unit and it was alleged that the same was effluent generated from the Process house in the name of M/s Shubhlaxmi Processors Pvt Ltd.


Name of Plant-ShubhLaxmi Processors Pvt.Ltd.


Address- Araji No. 1678,1688,1692 to 1695,1701,4097/1695,1697,1698 Village - Hamirgarh, Tehsil-Hamirgarh, District-Bhilwara

Date of Inspection: -09.04.2026

Findings of inspection are detailed as under:-

1. Aforesaid site was visited by the undersigned Board's officials in presence of the complainant on dated 09.04.2026 during night hours for verification of the contents of the complaint.
2. During inspection, it was observed that water of brownish muddy appearance was seeping out of the wall. Upon checking the primary characteristic of the water, it has been found that of TDS of the same was 960 ppm and was flowing from the drain located in the unit coming out from the nearby fields.
3. It has been also observed that, there was a damage in the wall of the unit at the bottom due to which this muddy water was leaking into the field.
4. Upon observing primarily, by looking at the water and its primary characteristic, it has not been appeared as effluent of the process. However, unit representative was called at the site and he was instructed to repair the wall by 12.04.2026 and inform the office accordingly.
6. GPS coordinates of photographs taken during inspection are enclosed.


(SourabhParwani)
Young Intern


(KanhayalalKumawat)
JEE

C/s


(Deepak Dhanetwal)
SEE & Regional Officer



Latitude: 25.186175
Longitude: 74.612184
Elevation: 429.89±5.53 m
Accuracy: 4.1 m
Time: 09-04-2026 23:08
Note: Subh laxmi

Powered by NoteCam



Latitude: 25.186084
Longitude: 74.611995
Elevation: 419.19±4.0 m
Accuracy: 3.166 m
Time: 09-04-2026 23:04
Note: Subh laxmi

Powered by NoteCam



REGIONAL OFFICE
RAJASTHAN STATE POLLUTION CONTROL BOARD
18, Azad Nagar, Pannadhai Circle, Bhilwara - 311001

Ph: 01482-241159

Date: 10/04/2026

SITE OBSERVATION

M/s Subh laxmi Processors

Sub.:- Observation during the inspection dated 09/04/2026.

With reference to the above, the unit was inspected on 09/04/2026 and following observations were discussed:

1. It has been found that water from from the boundary wall was seeping out in the agriculture field of complainant Shree Kishan Lal Gurjar. Though TDS was 960 ppm . However, you are directed to repair the wal and report the same to this office by 12.04.2026
- 2.
- 3.
- 4.
- 5.
- 6.

You are therefore advised to take action on the above points within 2 days and inform the action taken in the matter to the Board.

Kanhaiya Lal Kumawat JEE

This is an electronically generated document and does not require signature.