



क्षेत्रीय कार्यालय
REGIONAL OFFICE

स्थान राज्य प्रदूषण नियंत्रण मण्डल, भीलवाडा
RAJASTHAN STATE POLLUTION CONTROL BOARD, BHILWARA
Email:-rorpcc.bhilwara@gmail.com
www.environment.rajasthan.gov.in



Registered Letter/Post

RPCB/RO/BHL/Gen-109/2769-2772

Date- 23/11/25

1. Joint Director,
Department of Information and Technology (DoIT),
Bhilwara.
2. General Manager,
BSNL, Bhilwara.

Sub-Regarding Survey Report for the installation of camera at various critical locations to monitor the illigle discharge of effluent by the process houses located under the jurisdiction of this office.

Ref- 1. Meeting held on dated 16.09.2025 and 28.11.2025 under the chairmanship of District collector Bhilwara.
2. District collector, Bhilwara letter 28.11.2025.

Sir,

In Reference to above, it is to inform that Survey for the installation of camera at various critical locations to monitor the illigle dischsarge of effluent by the process house has been carried out by this office. Detaild survey report is enclosed herewith this letter and submitted for the further necessary action regarding feasibility of the locations.

It is also requested to provide the necessary assistant,in reference to above subjected matter, for the installation of PTZ cameras.

Sincerely,


Regional Officer


Regional Officer

Copy to following for the information please.

1. Member Secretary, RSPCB, HO Jaipur.
2. District Collector, Bhilwara.

18-19. पन्नाधाय सर्किल. आजादनगर. भीलवाडा

18-19, Near Pannadhaya Circle, Azad Nagar Bhilwara

For more information related to monitoring of textile process houses visit www.rspcbbhilwara.in



क्षेत्रीय कार्यालय
REGIONAL OFFICE
राजस्थान राज्य प्रदूषण नियंत्रण मण्डल, भीलवाडा
RAJASTHAN STATE POLLUTION CONTROL BOARD, BHILWARA
Email:-rorpcb.bhilwara@gmail.com
www.environment.rajasthan.gov.in



A

DETAILED SURVEY REPORT
ON IDENTIFICATION LOCATIONS FOR
INSTALLATION OF PTZ/CCTV CAMERAS



RAJASTHAN STATE POLLUTION CONTROL BOARD, BHILWARA



BACKGROUND OF COMMITTEE-

1. During the 3rd Session of the 16th Rajasthan Legislative Assembly, Shri Uday Lal Bhadana, Hon'ble MLA Mandal, raised the issue regarding the disposal of industrial wastewater generated from textile processing units.
2. In response of this, Shri Sanjay Sharma, Hon'ble Minister of Forest, Environment, Science & Technology (Independent Charge), Government of Rajasthan, has assured the house that a four member committee as mentioned under, would be constituted to lookout in this this matter.
3. In compliance with the assurance given in the House by Hon'ble Minister, Department of Administrative Reforms, Government of Rajasthan, vide order dated 28.08.2025, constituted a four-member committee. (Copy Enclosed- Annexure-A)

COMPOSITION OF COMMITTEE: -

1. District Collector, Bhilwara - Chairperson
2. General Manager, District Industries Centre, Bhilwara - Member
3. Joint Director, Agriculture Department, Bhilwara - Member
4. Regional Officer, Rajasthan State Pollution Control Board (RSPCB), Bhilwara - Member Secretary

4. In compliance to order dated 28.08.2025, meeting was held on 16.09.2025 under the chairmanship of the District Collector, Bhilwara. (Copy of minutes of meeting enclosed- Annexure-B).

ACTION TAKEN IN REFERENCE TO MINUTES OF MEETING (POINT NO.-10) DATED 16.09.2025 DURING THE MEETING: -

1. In reference to the directions issued during the Committee meeting held on 16.09.2025, follow-up meeting was convened by the District Collector Sir, Bhilwara, on 28.11.2025. During the meeting, three-member committee was constituted. The details of the **three-member committee** are as follows: (Copy of the letter enclosed- Annexure-C)
 - a) **Regional Officer, Rajasthan State Pollution Control Board (RSPCB), Bhilwara** - Directed to identify the HOT-Spots/Critical locations and submit the report of the locations with GPS tagged photographs.
 - b) **Joint Director, DoIT, Bhilwara**- Directed to identify the required equipment for digital infrastructure, monitoring design, and the integration of feeds into the control room, and take necessary action for their installation and to provide technical support for planning and execution of the proposed system.
 - c) **General Manager, BSNL, Bhilwara**- Directed To provide digital connectivity, infrastructure support, and other ICT-related requirements for online data transmission and monitoring.



Committee was directed to submit the **Consolidated Proposal** report to the District Collector, Bhilwara within **15 days** for further approval under DMFT.

2. In compliance with the directions issued during the meeting 16.09.2025 and 28.11.2025. Critical locations at the Chitter Raod, Ajmer Road and Pur Road, where the mostly textile industries situated and complaints received regarding disposal of industrial effluent outside the premises, were identified. (List enclosed-Annexure-D)

SCOPE OF THE WORK-

Benefit and utility of the installations of cameras- Above listed locations were selected based on the maximum possibility of discharge of industrial effluent discharged by the process house situated at the various locations under the jurisdiction of this office.

1. Better monitoring of the drains from the adjoining of the industries, here the high possibility of discharge of effluent, especially during the rainy season.
2. Better monitoring of tankers, complaints also received regarding effluents transport from the industries to outside the premises through tankers and same is being discharged at unknown locations.
3. Better monitoring of canal passing from the industries, here the high possibility of discharge of effluent during the winter season when the canals were flowing.
4. Better monitoring of the spraying activities of the effluent within the premises and nearby open plots.
5. Better monitoring of direct discharge of effluent into open field and near by area of the premises.

CAMERA LOCATION SELECTION CRITERIA-

1. Covering the maximum drains, flowing from adjoining of the industries.
2. Covering the critical locations/industries having the high possibility to direct discharge into open field or having the possibility of water spraying activity.
3. Covering the maximum canals, flowing from the industries.
4. Covering the maximum locations where the high possibility of discharge of effluent through tankers.



क्षेत्रीय कार्यालय
REGIONAL OFFICE
राजस्थान राज्य प्रदूषण नियंत्रण मण्डल, भीलवाडा
RAJASTHAN STATE POLLUTION CONTROL BOARD, BHILWARA
Email:-rorpcb.bhilwara@gmail.com
www.environment.rajasthan.gov.in



Total 23 camera locations were identified based on the above criteria and the details are as-

Location-1

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
M/s Kanchan India Pvt. Ltd.	Village-Gudda, Tehsil-Mandal, Ajmer Road, Bhilwara	Back side wall of Unit that in near railway track	Drain In the premises and rain water outlet of unit	25.43399	74.594735	1. Direct discharge into agriculture field. 2. Water spraying activities. 3. Discharge through tanker

Visiting officials-

1. Shilpa Baheti, JEE
2. Rohit Singh, JEE



Location-2

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
M/s Saileela Processors Private Limited	Village- Gudda, Tehsil- Mandal , Ajmer Road, Bhilwara	Back side wall towards Chatrikheda Village	Natural Drain flowing along with boundary wall of the unit.	25.43234	74.606234	1. Direct discharge into agriculture field. 2. Water spraying activities. 3. Discharge through tanker
Visiting officials-						1. Shilpa Baheti, JEE 2. Rohit Singh, JEE



Location-3

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
Janki Corp Limited	MandapiyaChauraha, Chittor Road, Bhilwara	1. At boundary wall near MEE	1. Solar Panel area 2. Agriculture Field near unit.	25.2699 62	74.6336 63	1. Direct discharge into agriculture field. 2. Water spraying activities. 3. Discharge through tanker

Visiting Official-

1. Jitendr Singh Meena, AEE



Location-4

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
Sona Selection	18 Km Stone Chittor Road, Bhilwara	1. At the corner of back side boundary wall	1. Drain flowing from back side of unit. 2. Open Field back side. 3. ETP area	25.19794	74.612702	1. Direct Discharge into open field. 2. Water spraying activities. 3. Discharge through tanker. 4. Direct Discharge of effluent into Drain.

Visiting Official-

1. Jitendr Singh Meena, AEE



Location-5

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
Sangam India Limited	BiliyaKalanBhilwara	1. At the gate no. 8 of Denim plant	1. Road side drain	25.22473	74.622778	1. Discharge through tanker.
Visiting Official-						
1. Jitendr Singh Meena, AEE						



Location-6

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
Sunrakshakk Industries India Ltd(AK Spintex Limited)	14 Km Stone, BiliyaKalan, Chittor Road, Bhilwara	1. At the ETP side gate of Unit	1. Drain coming from the village located upstream side of unit. 2. Drain comming from the Sangam India Ltd side. 3. ETP area of unit	25.23226	74.622248	1. Direct discharge of effluent by the Sangam India Ltd into drain. 2. Direct discharge of effluent by the AK spintex into drain.

Visiting Official-

1. Jitendr Singh Meena, AEE



Location-7

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
Puja Spintex Ltd	13 KM Stone, Chittor Road, Bhilwara	1. At the Boundary wall, Near RO reject Tank	1. Canal Passing through the unit. 2. Agriculture Field near unit. 3. Premises open area	25.246394	74.622613	1. Direct Discharge into open field. 2. Water spraying activities. 3. Discharge through tanker. 4. Direct Discharge of effluent into Canal.

Visiting Official-

1. Jitendr Singh Meena, AEE



Location-8

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
Puja Spintex Ltd	13 KM Stone, Chittor Road, Bhilwara	1. At the corner of back side boundary wall near solar panel	1. Solar Panel area 2. Agriculture Field near unit.	25.241596	74.624855	1. Direct Discharge into open field. 2. Water spraying activities. 3. Discharge through tanker.

Visiting Official-

1. Jitendr Singh Meena, AEE



Location-9

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
SanwariyaJitexfab Ltd	Chittor Road, Guwardi, Bhilwara	1. At the Boundary wall, Near New ETP	1. Open Field back side. 2. ETP area	25.246492	74.623165	1. Direct Discharge into open field. 2. Water spraying activities. 3. Discharge through tanker.

Visiting Official-

1. Jitendr Singh Meena, AEE



Location-10

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
Sona Processors	12 KM Stone, Chittor Road, Bhilwara	1. At the Boundary wall corner.	1. Drain flowing adjecent to unit. 2. Open Field back side.	25.250528	74.628465	1. Direct Discharge into open field. 2. Water spraying activities. 3. Discharge through tanker. 4. Direct Discharge of effluent into Drain.

Visiting Official-

1. Jitendr Singh Meena, AEE



Location-11

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
Bhilwara Spinners Limited	Spl-1, RIICO Industrial Area, Pur Road, Bhilwara Tehsil:Bhilwara District:Bhilwara	In front of biological tank at Railing	Open Field area at back side of BSL & ETP Area	25.32756	74.5793	1. Direct discharge into open field.

Visiting Official-

1. Shweta Dadheech, SO



Location-12

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
M/s Ronak Processors Private Limited	G-I38 to 142, 4th Phase. RIICO Industrial Area Pur Road. Bhilwara.	(i) At Front Gate	RIICO Drain flowing from adjoin to unit	25.33086	74.5803	Direct Discharge into Drain
Visiting Official-						
1. Shweta Dadheech, SO						



Location-13

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
SWASTIKA SUITINGS PVT.LTD	7-14,Industrial Area, PurRoad,Bhilwara	(ii) At Wall near RO reject tank	ro rejection tank area & area behind wall	25.31823	74.5747	1. Direct Discharge into open field. 2. Water spraying activities.

Visiting Official-

1. ShwetaDadheech, SO



Location-14

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
Rolex Processors Pvt. Ltd.	13-14 KM Stone Gangapur Road, Village-Pur, Tehsil-Bhilwara, District-Bhilwara.	At wall near Vacant plot	all vacant area covered, possibility of discharge	25.283	74.5202	1. Direct Discharge into open field. 2. Water spraying activities. 3. Direct Discharge into Drain

Visiting Official-

1. Shweta Dadheech, SO



Location-15

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
Anant Process	Chittor road, Bhilwara	At the Boundary wall	Back side of industry and Railway Track	25.277441	74.637949	Direct discharge into open area
Visiting Official-						
<ol style="list-style-type: none"> 1. KritiakaSomawat, SO 2. KanhayaLalKumawat, JEE 						



Location-16

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
Super Gold	Chittor road, Bhilwara	At the ETP area	1. ETP area 2. Drain flowing from adkoing to unit	25.262965	74.641033	1. Direct discharge into open area 2. Water spraying activity 3. Direct discharge into drain
Visiting Official-						
3. KritiakaSomawat, SO 4. KanhayaLalKumawat, JEE						



Location-17

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
BSL	Chittor road, Bhilwara	At the Boundary wall	1. Back side of area of industry 2. Raiilway track 3. T point	25.23618	74.626861	1. Direct discharge into natural nalla 2. Water spraying activity

Visiting Official-

1. KritiakaSomawat, SO
2. KanhayaLalKumawat, JEE



Location-18

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
BSL	Chittor road, Bhilwara	At near boundary wall at solar area	1. Nalla between RSWM and BSL 2. Open area backside of RSWM and BSL	25.232614	74.626202	1. Direct discharge into natural nalla

Visiting Official-

1. KritiakaSomawat, SO
2. KanhayaLalKumawat, JEE



Location-19

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
RSWM	Chittor road, Bhilwara	1. At the Boundary wall corner.	Nack side of industry and bridge area	25.228819	74.624963	1. Discharge through tanker.

Visiting Official-

1. KritiakaSomawat, SO
2. KanhayaLalKumawat, JEE



Location-20

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
Sarvoday India Ltd (Old Name- Shree Charbhuja Processor)	Growth Center, Hammirgarh, Bhilwara	At near solar area	Solar area of industry and near by open area	25.22897	74.631566	1. Direct discharge into open area 2. Water spraying activity
Visiting Official-						
<ol style="list-style-type: none"> 1. KritiakaSomawat, SO 2. KanhayaLalKumawat, JEE 						



Location-21

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
M/s Sarvoday India Ltd (Old Name- Shree Charbhija Processor)	Growth Center, Hammirgarh, Bhilwara	At near boundary wall	Side plot of Sarvoday and chairman process	25.230597	74.63328	Direct discharge into open area by flexible pipe.
Visiting Official-						
<ol style="list-style-type: none"> 1. KritiakaSomawat, SO 2. KanhayaLalKumawat, JEE 						



Location-22

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
Chairman Process	Growth Center, Hammirgarh, Bhilwara	At near boundary wall	Front side of industry and nalla	25.232722	74.633712	Direct discharge into natural nalla
Visiting Official-						
1. KritiakaSomawat, SO 2. KanhayaLalKumawat, JEE						



Location-23

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
Ranjan Polyester	Chittor road, Bhilwara	1. At the Boundary wall corner.	1. Back side Nala 2. Canal flowing from adjoin to the boundary of unit	25.244488	74.6280 45	1. Direct discharge into natural nalla 2. Direct discharge into Canal
Visiting Official-						
1. KritiakaSomawat, SO 2. KanhayaLalKumawat, JEE						



Location-24

Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
Ranjan Polyester	Chittor road, Bhilwara	At near MEE area	Back side of nalla	24.6765	74.688777	Direct discharge into natural nalla

Visiting Official-

1. KritiakaSomawat, SO
2. KanhayaLalKumawat, JEE



Location-25

Name of Location	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
Mangrop Police Station	Mangrop, Bhilwara	At near boundary wall near Banas River at police station	Banas river bridge	25.245471	74.690034	1. Discharge through tanker.
Visiting Official-						
1. KritiakaSomawat, SO 2. KanhayaLalKumawat, JEE						



Annexure - A

राजस्थान-राजकार
प्रशासनिक रुधार (अनुगाम-3) विभाग

क्रमांक पं. 6(16)प्र.सु./अनु-3/2019-03979/ज

जयपुर, तिगांक:- 28/08/2025

आदेश:-

भीलवाड़ा जिले में स्थित औद्योगिक इकाइयों विशेष रूप से कपड़ा प्रोसेसिंग यूनिट के द्वारा प्रदूषण की समस्या के संबंध में सभी संबंधित से चर्चा कर यांचित कार्यवाही हेतु सुझाव देने के लिए जिला स्तरीय समिति का गठन निम्नानुसार किया जाता है:-

1. जिला कलक्टर, भीलवाड़ा
2. महाप्रबंधक, जिला उद्योग केन्द्र, भीलवाड़ा।
3. संयुक्त निदेशक, कृषि विभाग, भीलवाड़ा।
4. क्षेत्रीय अधिकारी, राजस्थान राज्य प्रदूषण नियंत्रण मंडल, भीलवाड़ा। (सदस्य सचिव)

उक्त समिति अपनी रिपोर्ट अतिरिक्त मुख्य सचिव, पर्यावरण एवं जलवायु परिवर्तन विभाग, राजस्थान सरकार को प्रस्तुत करेगी। उक्त समिति का कार्यकाल समिति की रिपोर्ट प्रस्तुत करने तक रहेगा।

इस समिति का प्रशासनिक विभाग पर्यावरण एवं जलवायु परिवर्तन विभाग, राजस्थान सरकार होगा।

राज्यपाल की आज्ञा से,

(शैफाली कुशवाहा)
शासन उप सचिव

प्रतिलिपि निम्नांकित को सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित है:-

1. सचिव, राज्यपाल महोदय, राजस्थान सरकार, जयपुर।
2. अतिरिक्त मुख्य सचिव, मुख्यमंत्री, राजस्थान सरकार, जयपुर।
3. संयुक्त सचिव, मुख्य सचिव कार्यालय, राजस्थान सरकार, जयपुर।
4. निजी सचिव, अतिरिक्त मुख्य सचिव, पर्यावरण एवं जलवायु परिवर्तन विभाग, राजस्थान सरकार, जयपुर।
5. निजी सचिव, प्रमुख शासन सचिव, उद्योग विभाग, राजस्थान सरकार, जयपुर।
6. निजी सचिव, शासन सचिव, कृषि विभाग, राजस्थान सरकार, जयपुर।
7. जिला कलक्टर, भीलवाड़ा।
8. क्षेत्रीय अधिकारी, राजस्थान राज्य प्रदूषण नियंत्रण मंडल, भीलवाड़ा।
9. महाप्रबंधक, जिला उद्योग केन्द्र, भीलवाड़ा।
10. संयुक्त निदेशक, कृषि विभाग, भीलवाड़ा।

शासन उप सचिव

Signature valid

Digitaly signed by Shefali Kush
Designation : Deputy Secretary
Government
Date: 2025.08.28 17:36:44 IST
Reason: Approval

नारी क्लियर

1/9/25

RajKaj Ref No.:
17034945
eSign 1.0

इकाइया
कृषि विभाग
जिला कलक्टर
भीलवाड़ा



बैठक सूचना

प्रशासनिक सुधार विभाग, राजस्थान सरकार के पत्र दिनांक 28.08.2025 के द्वारा भीलवाडा जिले में स्थित औद्योगिक इकाइयों विशेष रूप से कपड़ा प्रोसेसिंग इकाइयों के द्वारा प्रदूषण की समस्या के सम्बन्ध में सभी सम्बंधित पक्षों से चर्चा की जाकर वांछित कार्यवाही हेतु सुझाव देने के लिए जिला स्तरीय समिति का गठन किया गया है :-

१. जिला कलेक्टर, भीलवाडा ।
२. महाप्रबंधक, जिला उद्योग केंद्र, भीलवाडा ।
३. संयुक्त निदेशक, कृषि विभाग, भीलवाडा ।
४. क्षेत्रीय अधिकारी, राजस्थान राज्य प्रदूषण नियंत्रण मण्डल, भीलवाडा – सदस्य सचिव ।

राज्य सरकार के उक्त आदेश की अनुपालना में दिनांक 15 सितम्बर 2025 को सां� 05:00 वजे क्षेत्रीय कार्यालय, राजस्थान राज्य प्रदूषण नियंत्रण मण्डल, भीलवाडा के सभागार में माननीय सांसद महोदय भीलवाडा, माननीय विधायक महोदय, मांडल, माननीय विधायक महोदय, सहाडा, माननीय विधायक महोदय, भीलवाडा, एवं माननीय विधायक महोदय, आसांद की उपस्थिति में अन्य संबंध पक्षों के साथ उक्त जिला स्तरीय समिति की एक बैठक प्रस्तावित की गयी है ।

अतः आप सभी श्रीमान से निवेदन है कि, आप सभी अपने बहुमूल्य सुझावों के साथ इस बैठक में उपस्थित होने का श्रम करावें ।

सादर ।

दीपक धनेटवाल /Deepak Dhanetwal

वरिष्ठ पर्यावरण अभियंता एवं क्षेत्रीय अधिकारी / SEE & Regional Officer

Signature valid

18-19.पन्नाधाय सर्किल. आजादनगर. भीलवाडा
18-19, Near Pannadhaya Circle, Azad Nagar, Bhilwara

eSign 1.0

Digitally signed by Deepak Dhanetwal
Designation : Senior Environmental

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111

17724111



क्षेत्रीय कार्यालय
REGIONAL OFFICE
राजस्थान राज्य प्रदूषण नियंत्रण मण्डल, भीलवाडा
RAJASTHAN STATE POLLUTION CONTROL BOARD, BHIILWARA
Email:- rorpcb.bhilwara@gmail.com
www.environment.rajasthan.gov.in



रा. प्र. नि. मं/क्षे. का. भीलवाडा /सामान्य -13/राज-काज- संख्या

दिनांक :- 11-05-2025

प्रतिलिपि निम्न को प्रेषित करते हुए सादर निवेदन है कि उक्त बैठक में उपस्थित होने का श्रम करावें :-

१. माननीय सांसद महोदय, भीलवाडा ।
२. माननीय विधायक महोदय, मांडल/भीलवाडा / सहाडा /आसींद ।
३. श्रीमान जिला कलेक्टर महोदय, भीलवाडा ।
४. श्रीमान महाप्रबंधक महोदय, जिला उद्योग केंद्र भीलवाडा ।
५. श्रीमान संयुक्त निदेशक महोदय, कृषि विभाग, भीलवाडा ।
६. महासचिव महोदय, मेवाड़ चैम्बर ऑफ़ कॉमर्स एवं इंडस्ट्रीज, भीलवाडा ।

प्रतिलिपि निम्न को सूचनार्थ सादर प्रेषित है :-

१. श्रीमान सचिव महोदय, माननीय राज्यपाल महोदय, राजस्थान सरकार, जयपुर ।
२. श्रीमान अतिरिक्त मुख्य सचिव महोदय, माननीय मुख्यमंत्री महोदय, राजस्थान सरकार, जयपुर ।
३. निजी सचिव महोदय, माननीय वन, पर्यावरण एवं विज्ञान प्रौद्योगिकी मंत्री (स्वतंत्र प्रभार) महोदय, राजस्थान सरकार, जयपुर ।
४. श्रीमान संयुक्त सचिव महोदय, मुख्य सचिव कार्यालय, राजस्थान सरकार, जयपुर ।
५. निजी सचिव महोदय, अतिरिक्त मुख्य सचिव, पर्यावरण एवं जलवायु परिवर्तन विभाग, राजस्थान सरकार, जयपुर ।
६. निजी सचिव महोदय, श्रीमान अध्यक्ष महोदय, राजस्थान राज्य प्रदूषण नियंत्रण मंडल, जयपुर ।
७. श्रीमान सदस्य सचिव महोदय, राजस्थान राज्य प्रदूषण नियंत्रण मंडल, जयपुर ।
८. निजी सचिव महोदय, श्रीमान प्रमुख शासन सचिव महोदय, उद्योग विभाग, राजस्थान सरकार, जयपुर ।
९. निजी सचिव महोदय, श्रीमान शासन सचिव महोदय, कृषि विभाग, राजस्थान सरकार, जयपुर ।

क्षेत्रीय अधिकारी

Signature valid

18-19.पन्नाधाय सर्किल. आजादनगर. भीलवाडा
18-19, Near Pannadhaya Circle, Azaad Nagar, Bhilwara

Digitally signed by Deepak Dhanetwala
Designation / Senior Environmental
Engineer
Date: 2025.09.11 19:04:13 IST
Reason: Approved



बैठक कार्यवृत्त (मिनट्स ऑफ मीटिंग)

स्थान: जिला कलक्टर कार्यालय सभागार, भीलवाडा

दिनांक: 16.09.2025

विषय: भीलवाडा जिले में स्थित औद्योगिक इकाइयों विशेष रूप से कपड़ा प्रोसेसिंग उद्योगों द्वारा प्रदूषण की समस्या के संबंध में चर्चा करने हेतु समिति की बैठक।

पृष्ठभूमि- राजस्थान विधान सभा की 16वीं विधानसभा के द्वितीय सत्र के दौरान श्री उदय लाल भडाना माननीय विधायक, मांडल द्वारा वस्त्र प्रसंस्करण इकाइयों से निकलने वाले औद्योगिक अपशिष्ट जल निस्तारण का मुद्दा (प्रश्न संख्या 3959) उठाया गया। इस विषय में आधासन देते हुए श्रीमान संजय शर्मा, माननीय मंत्री वन, पर्यावरण, विज्ञान एवं प्रौद्योगिकी (स्वतंत्र प्रभार), राजस्थान सरकार द्वारा उक्त प्रकरण में चार सदस्यीय जाँच समिति गठित कर सभी जनप्रतिनिधियों एवं अन्य सम्बंधित पक्षों से चर्चा करते हुए नियमानुसार उचित कार्यवाही की जावेगी। इस क्रम में प्रशासनिक सुधार विभाग, राजस्थान सरकार, द्वारा जारी आदेश दिनांक 28.08.2025 के माध्यम से निम्नानुसार चार सदस्यीय समिति का गठन किया गया।

समिति के सदस्य

1. जिला कलक्टर, भीलवाडा।
2. महाप्रबंधक, जिला उद्योग केंद्र, भीलवाडा।
3. संयुक्त निदेशक, कृषि विभाग, भीलवाडा।
4. क्षेत्रीय अधिकारी, राजस्थान राज्य प्रदूषण नियंत्रण बोर्ड, भीलवाडा (सदस्य सचिव)।

जिला स्तरीय जाँच कमेटी की प्रथम बैठक दिनांक 16.09.2025 को आहुत की गयी, जिसमें समिति के नामित सदस्यों के अतिरिक्त निम्न जन प्रतिनिधियों को भी सादर आमंत्रित किया गया।

आमंत्रित सदस्य

1. श्री दामोदर अग्रवाल, माननीय सांसद, भीलवाडा।
2. श्री जब्बार सिंह सांखला, माननीय विधायक, आसिंद।
3. श्री लादूलाल पितलिया, माननीय विधायक, सहाडा।
4. श्री उदय लाल भडाना, माननीय विधायक, मांडल।
5. श्री अशोक कोठारी, माननीय विधायक, भीलवाडा।

Validity unknown

18-19.पन्नाधाय सर्किल. आजादनगर. भीलवाडा
18-19, Near Pannadhaya Circle, Azad Nagar, Bhilwara

eSign 1.0

Digitally signed by Deepak Dhanetwa
Designation : Senior Environmental
Date: 2025.09.24 7:13:36 IST
Reason: Approved



6. श्री आर के जैन, महासचिव, मेवाड़ चैंबर ऑफ कॉमर्स एंड इंडस्ट्री (MCCI), भीलवाडा (औद्योगिक इकाइयों के प्रतिनिधि)।

बैठक में चर्चा के मुख्य बिंदु

1. चर्चा के आरम्भ में सभागार में उपस्थित उक्त चारों माननीय विधयाको के अतिरिक्त उपस्थित माननीय विधायक मांडलगढ़ माननीय, विधायक जहाजपुर माननीय, विधायक शाहपुरा द्वारा आपत्ति दर्ज की गयी कि, इस समिति में हमें भी सम्मिलित किया जाए। श्रीमान जिला कलक्टर महोदय द्वारा क्षेत्रीय अधिकारी, RSPCB को निर्देशित किया गया कि, कपड़ा फैक्ट्री (Process Houses) भीलवाडा, मांडल, आसिंद व सहाड़ा विधानसभा क्षेत्र में स्थित हैं, परन्तु इनके अपशिष्ट जल से मांडलगढ़, जहाजपुर एवं शाहपुरा विधानसभा क्षेत्र भी प्रभावित होते हैं। अतः सभी माननीय विधायकों को समिति की बैठक में आमंत्रित किया जाये।
2. बैठक को आगे बढ़ाते हुए क्षेत्रीय अधिकारी, राजस्थान राज्य प्रदूषण नियंत्रण मण्डल, भीलवाडा द्वारा प्रजेटेशन के माध्यम से समिति को, औद्योगिक इकाइयों द्वारा वर्तमान औद्योगिक अपशिष्ट को निस्तारण करने के लिए में अपनाई जा रही पद्धति के बारे में अवगत कराया तथा वर्तमान में आ रही कुछ समस्या जैसे कुछ उद्योगों द्वारा दूषित जल को टैंकर एवं छिड़काव के माध्यम से निस्तारित करना इत्यादि है। इसके अतिरिक्त वरसात के समय इकाइयों से बाहर पानी छोड़े जाने की समस्या भी यदा-कदा पाई गयी है। इसके अतिरिक्त क्षेत्रीय अधिकारी द्वारा मांडल द्वारा निगरानी के लिए वर्तमान में किये जा रहे प्रयासों के साथ साथ 2023 से आज दिनांक तक दोषी इकाइयों के विरुद्ध की गयी कार्यवाही/अधिरोपित की गयी पर्यावरणीय क्षतिपूर्ति से सम्बंधित जानकारी साझा की गयी।
3. माननीय विधायक श्री उदय लाल भडाना ने अवगत कराया कि, इकाइयों के भीतर स्थित बोरवेल्स में दूषित जल डाला जा रहा है, जिससे किसानों की भूमि व कुओं का पानी प्रदूषित हो रहा है। इस पर क्षेत्रीय अधिकारी, RSPCB ने आश्वासन दिया कि सभी इकाइयों के बोरवेल्स के पानी जांच की जांच कर ऐसे बोरवेल चिन्हित कर दोषी इकाई को बंद करवाने की कार्यवाही सुनिश्चित की जाएगी।
4. इस क्रम में माननीय सांसद श्री दामोदर अग्रवाल ने निर्देशित किया कि, सभी इकाइयों में उच्चिष्ठ संयत स्थापित हैं, परंतु यह सुनिश्चित किया जाए कि, वे पूर्ण दक्षता एवं क्षमता से कार्य कर रहे हैं। इस क्रम को आगे बढ़ाते हुए माननीय सांसद महोदय द्वारा इकाई रीको हमीरगढ़ स्थित M/s Sarvodaya India Limited पर अधिरोपित की गयी पर्यावरणीय क्षतिपूर्ति को अनुचित एवं पक्षपात पूर्ण कार्यवाही बताया गया।

Validity unknown

18-19.पन्नाधाय सर्किल. आजादनगर. भीलवाडा
18-19, Near Pannadhaya Circle, Ajad Nagar, Bhilwara

17911895
eSign 10

Digitally signed by Deepak Dhanetwala
Designation : Senior Environmental
Date: 2025.09.24 17:13:36 IST
Reason: Approved



- इस पर क्षेत्रीय अधिकारी, RSPCB ने माननीय सांसद महोदय को समस्त तथ्यों से अवगत करते हुए अवगत किया कि, यह क्षतिपूर्ति 02.08.2024 एवं 03.09.2024 को मण्डल को प्राप्त शिकायतों एवं नियमित जांच की रिपोर्ट के आधार पर शून्य निशाव की शर्तों का उल्लंघन पाए जाने के कारणों से अधिरोपित की गई थी, एवं उस दिनांक तक इकाई का नया ETP प्रारम्भ नहीं हुआ था एवं निर्माणाधीन स्थिति में था। इसके अतिरिक्त क्षेत्रीय अधिकारी द्वारा यह भी अवगत कराया गया कि, उक्त समस्त कार्यवाही की संपूर्ण वीडियोग्राफी एवं फोटोग्राफी भी की गयी थी जिसके आधार पर मण्डल मुख्यालय द्वारा क्षतिपूर्ति राशि तय कर उसके पश्चात अधिरोपित की गयी।
- 5. माननीय विधायक मांडल, श्री उदयलाल भडाना, द्वारा उपस्थित सदन को अवगत करवाया कि प्रोसेस हाउस इकाइयों द्वारा पाइपलाइनों एवं अन्य संरचनाओं के माध्यम से नालों एवं नदियों में काला पानी(दूषित जल) छोड़ा जा रहा है। उन्होंने यह भी अवगत कराया कि, जिन इकाइयों द्वारा काला पानी (दूषित जल) छोड़ा जा रहा है उनकी जानकारी वे उपलब्ध कराएँगे, उन पर प्रदूषण नियंत्रण बोर्ड द्वारा कड़ी कार्यवाही की जाए। इस क्रम को आगे बढ़ाते हुए श्रीमान जिला कलेक्टर महोदय द्वारा क्षेत्रीय अधिकारी को निर्देशित किया गया कि, उपस्थित माननीय सांसद महोदय एवं समस्त माननीय विधायकों से संपर्क कर उनके द्वारा चिन्हित की गयी समस्त दोषी इकाइयों की सूची ली जाकर उनपर कार्यवाही की जानी सुनिश्चित की जाए।
- 6. क्षेत्रीय अधिकारी द्वारा सदन को यह अवगत कराया गया कि, हाल ही में कुछ प्रकरण ऐसे आये हैं जिसमें कुछ अज्ञात इकाइयों विशेषकर चित्तोरगढ़ रोड स्थित इकाइयों द्वारा टैंकर के माध्यम से दूषित जल डालने की शिकायत प्राप्त हुई है एवं सत्यापित भी हुई है परन्तु इस तरह की इकाई चिन्हित नहीं की जा सकी क्यूंकि यह टैंकर हाईवे पर रात के समय इस तरह की गतिविधि करते हैं एवं मण्डल के सतर्कता दल द्वारा उन्हें पकड़ा जाना संभव नहीं हो पाता।
- 7. इस क्रम में क्षेत्रीय अधिकारी द्वारा कलेक्टर महोदय से निवेदन किया गया कि, इस क्रम में पुलिस विभाग को हाईवे पर रात के समय औचक निरीक्षण करने हेतु आदेशित करने का श्रम करावे। जिला कलेक्टर महोदय द्वारा, इस बावत पुलिस अधीक्षक महोदय को निर्देशित किया गया कि, इस तरह की गतिविधि पायी जाने पर सम्बन्धित पर तुरंत प्रभाव से कार्यवाही कर समिति को सूचित करे। इस पर उपस्थित माननीय सांसद महोदय एवं सभी माननीय विधायकों द्वारा सहमति जताई गयी।
- 8. इसके अतिरिक्त जिला कलेक्टर महोदय द्वारा यह भी निर्देशित किया गया कि, इकाइयों के औचक निरीक्षण हेतु मण्डल के सतर्कता दल के अतिरिक्त 3-4 सदस्यों के छोटे दल भी बनाये जाए एवं प्रत्येक

Validity unknown



दल में मण्डल का एक अधिकारी एवं अन्य अधिकारी जिला कलेक्टर महोदय द्वारा नामित रहेंगे जो अन्य विभागों से सम्बन्धित होंगे एवं उक्त दलों द्वारा इकाइयों का औचक निरीक्षण किया जाएगा और शर्तों के उल्लंघन पर इकाइयों को बंद करने की कार्यवाही अमल में लायी जायेगी।

9. जिला कलेक्टर महोदय द्वारा क्षेत्रीय अधिकारी को यह भी निर्देशित किया गया कि, यदि किसी इकाई द्वारा कोई पक्षा निर्माण कर दूषित जल नाले अथवा नदी में निश्चावित किया जा रहा है तो प्रशासन को सूचित कर जान्ता लेकर उसे तुडवाना सुनिश्चित किया जाए इसके अतिरिक्त ऐसे निश्चव की आशंका है एवं पक्षा निर्माण नहीं है तो उसे भी नियमानुसार बंद करने की कार्यवाही सुनिश्चित की जाए।
10. चर्चा को आगे बढ़ाते हुए जिला कलेक्टर महोदय द्वारा क्षेत्रीय अधिकारी को संदेहास्पद स्थान जहाँ पर इकाइयों द्वारा निश्चाव की सम्भावना बनी रहती है, उनको चिन्हित कर उन पर निगरानी हेतु सुदृढ़ कण्ट्रोल रूम की स्थापना की जाए एवं उन स्थानों पर CCTV लगाये जाए और मोनिटरिंग की जाए। इस क्रम में जिला कलेक्टर महोदय द्वारा क्षेत्रीय अधिकारी को इस बाबत एक प्रस्ताव बनाकर पेश करने हेतु निर्देशित किया एवं उपस्थित सभी सदस्यों द्वारा यह आम सहमती बनी कि उक्त हेतु वित्तीय स्वीकृति DMFT द्वारा जारी कर दी जायेगी।
11. इकाई प्रतिनिधियों का पक्ष रखने हेतु मेवाड़ चैंबर ऑफ कॉमर्स एंड इंडस्ट्री (MCCI) के प्रतिनिधि श्री आर के जैन द्वारा अवगत कराया कि, प्रत्येक इकाई में ETP, 3-stage, 4 Stage RO, MEE तथा ATFD स्थापित हैं जो दक्षता से कार्य कर रहे हैं।

- उन्होंने कहा कि उद्योगों के विरुद्ध अनावश्यक माहौल बनाया जा रहा है और कुछ तत्वों द्वारा हफ्ता वसूली की मांग की जा रही है।
- उन्होंने यह भी बताया कि भीलवाडा में स्थित उद्योग ETP तथा RO की तकनीक को लगातार उन्नत कर रहे हैं और अब RO Reject का निस्तारण MEE तथा ATFD से किया जा रहा है। उन्होंने निवेदन किया कि कमेटी के सदस्य, एक बार कमेटी राज्य के, एक बार राज्य के अन्य जिलों यथा पाली, बालोतरा, जोधपुर इत्यादि जो कि टेक्सटाइल हब है, उनका भी दौरा करे, भीलवाडा के उद्योग नियमों की पालना कर वेहद व्यवस्थित तरीके से effluent का उपचार कर उद्योग का सञ्चालन कर रहे हैं।

Validity unknown



12. आम सहमति से निम्न बिन्दुओं पर सहमति बनायी गयी :-

- माननीय सांसद एवं समस्त माननीय विधायको से संपर्क एवं परामर्श कर उन इकाइयों की सूची तैयार की जाए जो अनुपचारित जल छोड़ रही हैं। यह भी उल्लेखित किया जाए कि जल छोड़ने का स्रोत अस्थायी है या स्थायी (जैसे पाइपलाइन) के माध्यम से नालों अथवा नदियों में
 - अस्थायी संरचनाओं के मामले में नोटिस जारी कर नियमानुसार कार्यवाही की जाए।
 - स्थायी संरचनाओं के मामले में तुरंत ध्वस्तीकरण कराया जाए, आवश्यक सुरक्षा व बल /जाब्ता प्रशासन द्वारा उपलब्ध कराया जाएगा।
- औचक निरीक्षण (Sudden Inspection) हेतु छोटे छोटे जाँच दल गठित किये जायेंगे, जिसमें कार्यपालक मजिस्ट्रेट प्रशासन की तरफ से नियुक्त होंगे। प्रदूषण नियंत्रण मण्डल के प्रतिनिधि सहित 4 टीम बनाई जाएंगी, जिनमें प्रशासनिक अधिकारी/पुलिस अधिकारी भी सम्मिलित रहेंगे।
- यदि कोई इकाई शर्तों का उल्लंघन करती पाई जाती है तो तुरंत Consent to Operate प्रत्याहारित कर (Revoke) इकाई को बंद करने की कार्यवाही सुनिश्चित की जाएगी।
- इकाइयों की बेहतर निगरानी हेतु एक कंट्रोल रूम स्थित करने हेतु प्रस्ताव जिला कलेक्टर महोदय को प्रेषित किया जाए जिसमें CCTV कैमरा लगाना इत्यादि शामिल है एवं उक्त हेतु वित्तीय स्वीकृति DMFT फण्ड द्वारा जारी की जायेगी।

अंत में बैठक सधन्यवाद समाप्त हुई।

(दीपक धनेटवाल)

सदस्य सचिव - संयुक्त समिति एवं क्षेत्रीय अधिकारी

Validity unknown

18-19.पन्नाधाय सर्किल. आजादनगर. भीलवाडा
18-19, Near Pannadhaya Circle, Ajad Nagar, Bhilwara

eSign 1.0

Digitaly signed by Deepak Dhanetwa
Designation : Senior Environmental
Date: 2025.09.24 17:13:36 IST
Reason: Approved



क्षेत्रीय कार्यालय
REGIONAL OFFICE
राजस्थान राज्य प्रदूषण नियंत्रण मण्डल, भीलवाडा
RAJASTHAN STATE POLLUTION CONTROL BOARD, BHILWARA
Email:- rorpcb.bhilwara@gmail.com
www.environment.rajasthan.gov.in



रा. प्र. नि. मं/क्षे. का. भीलवाडा /सामान्य -13/राज-काज- संख्या

दिनांक :- 24.09.2025

प्रतिलिपि निम्न को सूचनार्थ सादर प्रेषित है:-

१. श्रीमान सचिव महोदय, माननीय राज्यपाल महोदय, राजस्थान सरकार, जयपुर।
२. श्रीमान अतिरिक्त मुख्य सचिव महोदय, माननीय मुख्यमंत्री महोदय, राजस्थान सरकार, जयपुर।
३. निजी सचिव महोदय, माननीय वन, पर्यावरण एवं विज्ञान प्रौद्योगिकी मंत्री (स्वतंत्र प्रभार) महोदय, राजस्थान सरकार, जयपुर।
४. माननीय सांसद महोदय, भीलवाडा।
५. माननीय विधायक महोदय, जहाजपुर/आसींद/मांडलगढ़/सहाडा/मांडल/शाहपुरा/भीलवाडा।
६. श्रीमान संयुक्त सचिव महोदय, मुख्य सचिव कार्यालय, राजस्थान सरकार, जयपुर।
७. निजी सचिव महोदय, अतिरिक्त मुख्य सचिव, पर्यावरण एवं जलवायु परिवर्तन विभाग, राजस्थान सरकार, जयपुर।
८. निजी सचिव महोदय, श्रीमान अध्यक्ष महोदय, राजस्थान राज्य प्रदूषण नियंत्रण मण्डल, जयपुर।
९. श्रीमान सदस्य सचिव महोदय, राजस्थान राज्य प्रदूषण नियंत्रण मण्डल, जयपुर।
१०. निजी सचिव महोदय, श्रीमान प्रमुख शासन सचिव महोदय, उद्योग विभाग, राजस्थान सरकार, जयपुर।
११. निजी सचिव महोदय, श्रीमान शासन सचिव महोदय, कृषि विभाग, राजस्थान सरकार, जयपुर।
१२. श्रीमान जिला कलेक्टर महोदय, भीलवाडा।
१३. श्रीमान पुलिस अधीक्षक महोदय, भीलवाडा।
१४. श्रीमान महाप्रबंधक महोदय, जिला उद्योग केंद्र भीलवाडा।
१५. श्रीमान संयुक्त निदेशक महोदय, कृषि विभाग, भीलवाडा।
१६. महासचिव महोदय, मेवाड़ चैम्बर ऑफ़ कॉमर्स एवं इंडस्ट्रीज, भीलवाडा।

क्षेत्रीय अधिकारी

Validity unknown

18-19.पन्नाधाय सर्किल. आजादनगर. भीलवाडा
18-19, Near Pannadhaya Chhatra Nada Nagar Bhilwara

eSign 1.0

Digitally signed by Deepak Dhanetwa
Designation : Senior Environmental
Date: 2025.09.24 17:13:36 IST
Reason: Approved

कार्यालय जिला कलक्टर, भीलवाड़ा

क्रमांक :- रा.प्र.नि.म./क्षे.का./भीलवाड़ा/ /सामान्य-109/Rajkaj Ref No.

दिनांक 28.11.2025

कार्यालय आदेश

माननीय मंत्री श्री संजय शर्मा, वन, पर्यावरण, विज्ञान एवं प्रौद्योगिकी) स्वतंत्र प्रभारी, राजस्थान सरकार द्वारा 16वीं राजस्थान विधानसभा के मानसून सत्र के दौरान, माननीय विधायक श्री उदयलाल भडाना मांडल (द्वारा कपड़ा-प्रसंस्करण इकाइयों से उत्पन्न औद्योगिक अपशिष्ट के निपटान से संबंधित प्रश्न संख्या 3959 के उत्तर में दिए गए आश्वासन तथा तत्पश्चात गठित जिलास्तरीय समिति की बैठक में लिए गए निर्णयों के अनुपालना में, सतत निगरानी और अन्य मॉनिटरिंग उद्देश्यों के लिए एक सशक्त नियंत्रण कक्ष) **Control Room**) की स्थापना और सी.सी.टी.वी. / PTZ कैमरे लगाने का निर्णय लिया गया है।

तदनुसार, क्रियान्विति बाबत निम्नलिखित निर्देश दिए जाते हैं:-

- क्षेत्रीय अधिकारी, रा.प्र.नि.म., भीलवाड़ा) सदस्य सचिव(- हॉट-स्पॉट स्थानों की जी.पी.एस. विवरण के साथ पहचान करते हुए विस्तृत योजना का समन्वय करेंगे।
- संयुक्त निदेशक, डी.ओ.आई.टी., भीलवाड़ा, - डिजिटल बुनियादी ढांचे, निगरानी डिज़ाइन और कंट्रोल रूम में फीड के एकीकरण के लिए आवश्यक उपकरणों का निर्धारण कर स्थापना हेतु आवश्यक कार्य करेंगे।
- महाप्रबंधक, भारत संचार निगम लिमिटेड (बी.एस.एन.एल.), - भीलवाड़ा, डिजिटल बुनियादी ढांचे, निगरानी डिज़ाइन और कंट्रोल रूम में फीड के एकीकरण के लिए तकनीकी मार्गदर्शन एवं आवश्यक सहयोग प्रदान करेंगे।

उपरोक्त अधिकारियों को निर्देश दिया जाता है कि, वे 15 दिनों के भीतर डी.एम.एफ.टी. (DMFT) के तहत अनुमोदन हेतु एक समेकित कार्यान्वयन प्रस्ताव (Consolidated Implementation Proposal) तैयार करवा कर प्रस्तुत करना सुनिश्चित करावें।

(जसमीत सिंह संधू
जिला कलक्टर, भीलवाड़ा)

प्रतिलिपि निम्न को सूचनार्थ एवं आवश्यक अनुपालना हेतु प्रेषित है-

- अतिरिक्त जिला कलक्टर, (प्रशासन), भीलवाड़ा |
- क्षेत्रीय अधिकारी, रा.प्र.नि.म., भीलवाड़ा |
- महाप्रबंधक, जिला उद्योग केंद्र, भीलवाड़ा |
- संयुक्त निदेशक, कृषि विभाग, भीलवाड़ा |
- संयुक्त निदेशक, डी.ओ.आई.टी., भीलवाड़ा |
- महाप्रबंधक, भारत संचार निगम लिमिटेड (बी.एस.एन.एल.) भीलवाड़ा |

Signature valid

Digitally signed by Jasmeet Singh
Sandhu
Designation : Collector & District
Magistrate
Date: 2025.11.28 11:09:00 IST
Reason: Approved

RajKaj Ref No.:
19100058

जिला कलक्टर, भीलवाड़ा

Annexure - D

Sr. No.	Name of unit	Address	Camera Location	Area covered by the camera	Latitude	Longitude	Issues likely to reduced by installing Camera here
1	M/s Kanchan India Pvt. Ltd.	Village- Gudda, Tehsil- Mandal, Ajmer Road, Bhilwara	Back side wall of Unit that in near railway track	Drain In the premises and rain water outlet of unit	25.43399	74.594735	1. Direct discharge into agriculture field. 2. Water spraying activities. 3. Discharge thorough tanker
2	M/s Sadleela Processors Private Limited	Village- Gudda, Tehsil- Mandal, Ajmer Road, Bhilwara	Back side wall towards Chatrikheda Village	Natural Drain flowing alongwith boundary wall of the unit	25.43234	74.606234	1. Direct discharge into agriculture field. 2. Water spraying activities. 3. Discharge thorough tanker
3	Janki Corp Limited	Mandapiya Chauraha, Chittor Road, Bhilwara	1. At boundary wall near unit. 2. MEE/ ATFD 3. Agriculture Field near unit.	25.269962	74.633663	1. Direct discharge of effluent into Canal. 2. Direct discharge into agriculture field.	
4	Sona Selection	18 Km Stone Chittor Road, Bhilwara	1. At the corner of back side boundary wall 2. Open Field back side. 3. ETP area	25.19794	74.612702	1. Direct discharge into open field. 2. Water spraying activities. 3. Discharge thorough tanker. 4. Direct discharge of effluent into Drain.	
5	Sangam India Limited	Biliya Kalan Bhilwara	1. At the gate no. 8 of Denim plant	25.22473	74.622778	1. Discharge thorough tanker.	
6	Sunrakshakk Industries India Ltd(AK Spintex Limited)	14 Km Stone, Biliya Kaln, Chittor Road, Bhilwara	1. At the ETP side gate of Unit	25.23226	74.622248	1. Direct discharge of effluent by the Sangam India Ltd into drain. 2. Direct discharge of effluent by the AK spintex into drain.	
7	Puja Spintex Ltd	13 KM Stone, Chittor Road, Bhilwara	1. At the Boundary wall, Near RO reject Tank 2. At the corner of back side boundary wall near solar panel	25.246394	74.622613	1. Direct discharge into open field. 2. Water spraying activities. 3. Discharge thorough tanker. 4. Direct discharge of effluent into Canal.	
8		Chittor Road, Guwadi, Bhilwara	1. At the Boundary wall, Near New ETP	25.241596	74.624855	1. Direct discharge into open field. 2. Water spraying activities. 3. Discharge thorough tanker.	
9	Sanwariya Ji texfab Ltd	Chittor Road, Guwadi, Bhilwara	1. Open Field back side.	25.246492	74.623165	1. Direct discharge into open field. 2. Water spraying activities. 3. Discharge thorough tanker.	
10	Sona Processors	12 KM Stone, Chittor Road, Bhilwara	1. At the Boundary wall corner.	25.250528	74.628465	1. Direct discharge into open field. 2. Water spraying activities. 3. Discharge thorough tanker. 4. Direct discharge of effluent into Drain.	
11	Bhilwara Spinners Limited	Sp1- RILCO Industrial Area, Pur Road, Bhilwara	in front of biological tank at Railing	25.32756	74.5793	1. Direct discharge into open field.	
12	M/s Ronak Processors	G-138 to 142, 4th Phase, District:Bhilwara	(i) At Front Gate	25.33086	74.5803		

13	SWASTIKA SUITINGS PVT LTD	7-14,Industrial Area, Pur Road,Bhilwara	(ii) At Wall near ro rejeciton tank	ro rejection tank area & area behind wall	25.31823	74.5747	
14	Rolex Processors Pvt Ltd	13-14 KM Stone Gangapur Road, Village- Pur, Tehsil- Bhilwara, District- Bhilwara.	(ii) At wall near Vacant plot	all vacant area covered, possibility of discharge	25.283	74.5202	
15	Anant Process	Chittor road, Bhilwara	At the Boundary wall	Back side of industry and Railway Track	25.277441	74.637949	Direct discharge into open area
16	Super Gold	Chittor road, Bhilwara	At the ETP area	1. ETP area 2. Drain flowing from adkoing to unit	25.262965	74.641033	1. Direct discharge into open area 2. Water spraying activity 3. Direct discharge into drain
17	BSL	Chittor road, Bhilwara	At the Boundary wall near STP	1. Back side of area of industry 2. Railiway track 3. T point	25.23618	74.626861	1. Direct discharge into natural nalla 2. Water spraying activity
18			At near boundary wall at solar area	1. Nalla between RSWM and BSL 2. Open area backside of RSWM and BSL	25.232614	74.626202	1. Direct discharge into natural nalla
19	RSWM	Chittor road, Bhilwara	1. At the Boundary wall corner.	Nack side of industry and bridge area	25.228819	74.624963	1. Dischage thorugh tanker.
20	Sarvoday	Growth Center, Hamnirgarh, Bhilwara	At near solar area	Solar area of industry and near by open area	25.222897	74.631566	Direct discharge into open area
21			At near boundary wall	Side plot of Sarvoday and chairman process	25.230597	74.63328	Direct discharge into open area by flexible pipe.
22	Chairman Process	Growth Center, Hamnirgarh, Bhilwara	At near boundary wall	Front side of industry and nalla	25.232722	74.633712	Direct discharge into natural nalla
23	Ranjan Polyester	Chittor road, Bhilwara	1. At the Boundary wall corner.	Back side nala	25.244488	74.628045	Direct discharge into natural nalla
24			At near MEE area	Back side of nalla	24.6765	74.688777	Direct discharge into natural nalla
25	Mangrop Police Station	Mangrop, Bhilwara	At near boundary wall near Banas River at police station	Banas river bridge	25.245471	74.690034	1. Dischage thorugh tanker.