

COMPLAINT VERIFICATION REPORT

DATE: 20.04.2026

Name of the industry: - M/s Saileela Processor Pvt Ltd

Address of the industry: - Village - Gudda, Teh. - Mandal, District - Bhilwara

As per the telephonic complaint received by Sh. Dinesh Gurjar, on 20.04.2026 regarding discharge of industrial effluent through in the rain water drain, that passes nearby M/s Saileela Processor Pvt Ltd and in compliance of directions received, undersigned Board officials inspected unit and verified the complaint on 20.04.2026.

During the inspection of aforesaid unit following observations were made-

- A rainwater drain passes near the premises of M/s Saileela Processor Pvt. Ltd.
- Total Dissolved Solids (TDS) were measured by handy hanna meter & it was observed as 2500 ppm(approx.).
- No direct discharge into the drain was observed during the inspection.
- No flexible pipes were found connected for discharge purposes.
- No wastewater or treated water discharge was observed either inside or outside the premises at the time of inspection.

Submitted for reference and further necessary action: -


(Kanhaya Lal Kumawat)

JEE

C/s


(Deepak Dhanetwal)
SEE & Regional Officer



Latitude: 25.482652
Longitude: 74.605203
Elevation: 475.5943.8 m
Accuracy: 2.083 m
Time: 20-04-2026 17:27
View: Salceda front



Latitude: 25.482652
Longitude: 74.605203
Elevation: 475.5943.8 m
Accuracy: 2.083 m
Time: 20-04-2026 17:29
View: Salceda front